

H.H. CHAMPLIN ESTATE
612 South Tyler Road
Enid
Garfield
Oklahoma

HALS OK-15
OK-15

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN LANDSCAPES SURVEY
National Park Service
U.S. Department of the Interior
1849 C Street NW
Washington, DC 20240-0001

HISTORIC AMERICAN LANDSCAPES SURVEY

H. H. CHAMPLIN ESTATE

HALS NO. OK-15

Location: 612 South Tyler Rd, Enid, Garfield County, Oklahoma.
Lat: 36.39045 Long -97.89357

Significance: Oilman and banker H. H. Champlin's home is a great example of the residential Tudor Revival style that was popular around the turn of the 20th Century, while the surrounding grounds are eclectic in style. The estate is situated in a neighborhood that exemplifies the architecture popular during the era. It is listed in the National Register of Historic Places, and is still in the family under the ownership of Joel Champlin.

History: Designed by architects R.W. Shaw and Norris Wheeler, the house was built from 1936 to 1939. Additional buildings were constructed later and include a greenhouse built in 1941 and a carport built in 1948. The original site plan was developed by Shaw when he designed the house. An interesting note is that bur oaks from the Marland Mansion in Ponca City, Oklahoma were transplanted to the Champlin Estate and planted along the front of the property. The mansion is largely unaltered from its original condition, while the eclectically styled landscape has received minor modifications over the years.

Sources: "National Register Properties in Oklahoma: H. H. Champlin House,"
<http://www.ocgi.okstate.edu/shpo/shpopic.asp?id=92001833> (accessed March 25, 2009).

"National Register of Historic Places Registration Form,"
<http://www.ocgi.okstate.edu/shpo/nhrpdfs/92001833.pdf> (accessed March 25, 2009).

"H. H. Champlin Estate." Historic American Buildings Survey, Library of Congress, Prints and Photograph Division, Washington, D.C. 20540,
<http://hdl.loc.gov/loc.pnp/hhh.ok0075> (accessed March 25, 2009).

Historian: Steve Eilers, March 25, 2009
3700 West 19th
Stillwater, OK 74074
steve.eilers@okstate.edu

Dr. Charles Leider
Professor and Director of the Landscape Architecture Program
Horticulture and Landscape Architecture Department
360 AG Hall

Stillwater, OK 74078-6027
Office: (405) 744-5420
charles.leider@okstate.edu



Front of estate (National Register Properties in Oklahoma website:
<http://www.ocgi.okstate.edu/shpo/shpopic.asp?id=92001833>, accessed March 21, 2009).



Front of estate (Enid Buzz website: <http://www.enidbuzz.com/enidhouses.html>, accessed March 25, 2009).